

OUT: 63399

SECRET

PRIO: DIA

1967 OCT 21 01 04Z

P 210049Z OCT 67  
 FM NPIC WASHDC  
 TO AIC 784a

[REDACTED] 25X1

B1  
 S E C R E T [REDACTED] CITE NPIC 2056  
 CPIR:NPIC SER:F00497BX MSN:006728 15OCT67H  
 DAY PHOTO. CAMERA ON 030938Z, OFF 042744Z. AMS SERIES L7015,  
 SHEETS 6142 I, 6242 III, IV, REF NPIC MSG 2025, DIG 160825Z,  
 OCT 67, SER.F00493. NPIC WILL NOT DISSEMINATE A HARD COPY  
 MISSION SUMMARY REPORT ON THIS MISSION. THIS IS A BLACK SHIELD  
 MESSAGE.

[REDACTED] 25X1

## PART I. SIGNIFICANT PHOTO INTERPRETATIONS

## B. NEW TARGETS AND SIGNIFICANT CHANGES

ZZZ01:BY-PASS UNDER CONSTRUC (NEW) SGM NONE CTY LA 165000N1060400E  
 A CLEARING OPERATION EXTENDS BETWEEN ROUTE 91 AT UTM XD121612  
 AND ANOTHER ROUTE 91 BY-PASS AT XD174599. AS BOTH CONNECTED  
 ROADS ARE PRESENTLY UNSERVICEABLE (SEE ITEM 3), THIS CONSTRUCTION  
 IS POSSIBLY IN ANTICIPATION OF THE END OF THE SOUTHWEST  
 MONSOON SEASON.

[REDACTED] 25X1

## PART II. OTHER PHOTO INTERPRETATIONS

## C. BONUS TARGETS COVERED

ZZZ02:ROUTE 9112 SERVICEABILITY SGM911B CTY LA 165900N1055800E  
 THE SOUTHERN HALF OF ROUTE 9112 REMAINS UNSERVICEABLE FOR THOROUGH-  
 TRAFFIC BETWEEN UTM XD025794 AND XD025758, AS A RESULT OF AIR  
 STRIKES AND WET WEATHER.

[REDACTED] 25X1

ZZZ03:ROUTE 91/911 SERVICEABILITY SGM 911B CTY LA 165755N1055750E  
 ROUTES 91 AND 911 REMAIN UNSERVICEABLE BETWEEN THE JUNCTIONS  
 WITH ROUTE 9112 AT 165755N 1055750E AND ROUTE 9 AT 164300N  
 1061010E, AS A RESULT OF AIR STRIKES AND WET WEATHER.

[REDACTED] 25X1

GP-1  
 S E C R E T [REDACTED]

[REDACTED] 25X1

//END OF MSG//

SECRET [REDACTED]

[REDACTED] 25X1

